



Below is a plot plan showing the layout of the equipment supplied and installed by Delta Tech Service.



NHT-3 low point drain list

1. 10-FV-001 low point drain
2. V-1015 emergency feed loop north of DOC station
3. Feed to E-1002B low point drain west of E-1002B, south end.
4. E-1002A feed out low point drain , west of E-1002A south end
5. Feed to E-1001C low point drain, west of E-1001C south end
6. 10-FV-007A low point drain west of F-1000
7. 10-FV-003 low point drain west of F-1000
8. F-1000 outlet west of furnace before spring can
- 9.
10. F-1000 outlet header south side
11. E-1001C shell side outlet low point south end
12. E-1002B shell side low point south end
13. E-1003 tube side low point drain south end
14. V-1010 alarm bridal low point drain
15. V-1010 gage glass bridal low point drain
16. 10- LV-011 low point drain
17. V-1015 alarm bridal low point drain
18. V-1015 gage glass bridal low point drain
19. 10-FC-016 low point drain
20. E-1004C tube side low point drain west end
21. V-1015 to C-1010 (E-1004 outlet) located north of V-1010 in overhead pipe way
22. P-1025B discharge line to C-1010 low point drain north of P-1025B
23. E-1004C shell side low point drain, south end
24. E-1004C shell side low point drain , north end
25. 10-FV-025 low point drain
26. V-1013 inlet line low point drain
27. 10-FV-017 low point drain
28. E-1016 inlet manifold low point drain
29. E-1016 inlet manifold low point drain
30. E-1016 outlet manifold low point drain
31. E-1016 outlet manifold low point drain
32. P-1000 case low point drain
33. P-1000A case low point drain
34. P-1000's Bypass low point drain
35. 10-LC-002 low point drain
36. 10-FV-001A low point drain
37. P-1001 low point drain D/S of discharge valve
38. P-1001A low point drain D/S of discharge valve
39. 3/4" bleeder D/S of 10FV001 check valves above C/V
40. P-1010 case low point drain
41. P-1010 case low point drain
42. P-1010A case low point drain
43. P-1010A case low point drain
44. E-1015 outlet low point drain
45. V-1010/V-1015 sour gas low point drain @ P/L
46. C-1010 O/H gas low point drain @ P/L
47. F-1010 outlet low point drain
48. PV-050 low point drain
49. K-1001 Suction low point
50. Sour Gas Low Point in pipe trench next to east bridge
51. K-1002 Suction Low point
52. E-1003's Tubeside common outlet low point drain
53. Product to tankage low point drain at Plot limit
54. Temporary hose from F-1000 inlet manifold to 3" header 3"
55. Temporary hose from F-1000 inlet manifold to 3" header 6"
56. R-1001 Inlet TI (pull thermowell and connect valve and hose)
57. C-2840 steam supply to C-1010 feed line
58. 6" 300 drop valve and connect temp hose from Delta Tech temp pump



*** All connections to look like this**